

MAINTENANCE HISTORY

Generation date: 2024/05/28

Plate Number **XJ-14-7P**
 Make **NISSAN**
 Model **Leaf**
 Vehicle Description **ACENTA 40kWh 5d**

DATE	MILEAGE	TYPE	DESCRIPTION
2023/04/08	0 KM	damage	<ul style="list-style-type: none"> Voorzijde Diversen Verlies Partieel
2023/02/01	0 KM	damage	<ul style="list-style-type: none"> Interieur Gordel(spanner) Interieurschade
2022/05/06	0 KM	damage	<ul style="list-style-type: none"> Bodem / onderzijde Rechts achter Spatbord RA tegen obstakel ger.
2021/09/08	0 KM	damage	<ul style="list-style-type: none"> Velg en/of band Links achter bandschade
2023/02/10	52839 KM	repair	<ul style="list-style-type: none"> APK zndr beurt - NVT - Uitvoeren Bandvervanging - NVT - Uitvoeren Ruitenw.blad V - versleten - Vervangen
2022/03/21	42430 KM	repair	<ul style="list-style-type: none"> Ruitenw.blad V - versleten - Vervangen Ruitenw.blad A - versleten - Vervangen
2021/11/26	38482 KM	repair	<ul style="list-style-type: none"> Bandbewerkingen - NVT - Uitvoeren
2021/09/08	35553 KM	repair	<ul style="list-style-type: none"> Bandvervanging - NVT - Uitvoeren Correctie/credit - NVT - Uitvoeren
2020/05/25	21456 KM	repair	<ul style="list-style-type: none"> WINTR>ZOMR Wiss - NVT - Uitvoeren

2019/01/18	2 KM	repair	<ul style="list-style-type: none">• ZOMR>WINTR Wiss - NVT - Uitvoeren
------------	------	--------	--------------------------------------------------------------------------------------------