



Inspection Report

Customer	BCA Sweden	Cosmetic Grade	3
Registration Number	RBU15W	Mechanical Grade	A

Vehicle Data

Audi e-tron 50 quattro, 313hk, 2020

Vehicle Identification Number	WAUZZZGE4LB039778	Odometer Reading	95545 km
First Registration / Construction Year	2020-07-17 / 2020-07-01	Inspection Date / Place	2025-04-16 / Kareby
Fuel Type		Gearbox Type	
Colour	Blue	Number of Keys	2
Service Book Available	Present	Service History	
Last Service Km / Date	91374 / 2024-12-20	Arrival Date	2025-04-15

Mounted Tires

Tyre / Wheel Type	Summer
	//R20 / 4 mm
	//R20 / 3 mm
	//R20 / 1 mm
	//R20 / 2 mm

Equipment

• Bluetooth	• Cruise control
• Digital Radio	• Electrically adjustable seats
• LED Headlamps	• Rear parking sensors
• Satellite navigation	• Front parking sensors
• Tow ball	• Metallic colour

Comments Test Drive

Comment

Checklist

Load Cover Missing	Testdriven
--------------------	------------


Damage

	Component	Damage
1	Tire / Back Left	Tire
2	Tire / Back Right	Tire
3	Door Step / Back Left	Interior / Scratched
4	Luggage Space Cover / Back	Interior / Missing
5	Tailgate Upholstery / Back	Interior / Stained
6	Door Step / Back Right	Interior / Dented
7	Wheel Arch / Front Right	Paint / Scratch / Scuff
8	Fender / Front Right	Paint / Scratch / Scuff
9	Shield / Front	Bodywork / Dent / Deformation
10	Rocker Panel / Center Left	Paint / Scratch / Scuff
11	Door / Back Left	Paint / Scratch / Scuff
12	Shield / Back	Paint / Scratch / Scuff
13	Rim / Front Right	Out of Bodywork / Scratch
14	Tire / Front Right	Tire
15	Rim / Back Left	Out of Bodywork / Scratch


Photo Documentation














1. Tire / Back Left

Tire



2. Tire / Back Right

Tire




3. Door Step / Back Left

Interior / Scratched



4. Luggage Space Cover / Back
Interior / Missing



5. Tailgate Upholstery / Back
Interior / Stained



6. Door Step / Back Right
Interior / Dented



7. Wheel Arch / Front Right

Paint / Scratch / Scuff



8. Fender / Front Right

Paint / Scratch / Scuff



9. Shield / Front


Bodywork / Dent / Deformation

Dented, unclipped, scratched/ bucklad, lös panel, repad



10. Rocker Panel / Center Left

Paint / Scratch / Scuff



11. Door / Back Left

Paint / Scratch / Scuff




12. Shield / Back

Paint / Scratch / Scuff



14. Tire / Front Right

Tire



15. Rim / Back Left

Out of Bodywork / Scratch